Oil Field Environmental Incident Summary

Incident: 20160220140036 Date/Time of Notice: 02/20/2016 14:00

Responsible Party: WHITING OIL AND GAS CORPORATION WHITING OIL AND GAS CORPORATION

Well Name: P BERGER 156-100-14-7-19-13H

Field Name: EAST FORK Well File #: 31023

Date Incident: 2/20/2016 Time Incident: 03:00 Facility ID Number:

Qtr: SW SE **WILLIAMS** Twp: 156 **Rna:** 100 **Sec:** 7 County:

Location Description:

Submitted By: Corissa Zimmer Received By:

Contact Person: Corissa Zimmer

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

0.2 Mile Distance Nearest Occupied Building: 0.2 Mile Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

> Spilled Units Recovered Units **Followup Units** 40 barrels

40 Barrels Oil

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/7/2016 Clean Up Concluded: 3/23/2016

Risk Evaluation: None noted.

Areal Extent:

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The spill was stopped and standing fluid is being vacuumed. A hydrovac truck will be used to complete cleaning the impacted area and tanks will be cleaned. Whiting will determine preventative future action when the root cause is fully determined.

Wastes Disposal Location: Wastes will be disposed at an approved facility.

Agencies Involved:

Updates

Date: 2/22/2016 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.